



Certificate No. : T-0071

ELECTRICAL RESEARCH AND DEVELOPMENT ASSOCIATION

(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India)
ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

Fax : +91 (0265) 2638382

E-mail : erda@erda.org

Web : http://www.erda.org



TEST REPORT

SHEET NO.: 1 OF 13

NAME & ADDRESS OF CUSTOMER M/s. Allianz Transformers Pvt. Ltd. Plot No. 11 & 12, Dewan Udyog Nagar, Chintupada, Mahim Village, Palghar (West), Dist.-Palghar, Maharashtra - 401 404	TEST REPORT NO.: RP-1516-020971	
	DATE : 03/09/2015	
	CUSTOMER REF. NO.: NIL	
	DATED : 27/08/2015	
	DATE OF SAMPLE RECEIPT	DATE OF TESTING
	20/08/2015	27/08/2015
SAMPLE DESCRIPTION DISTRIBUTION TRANSFORMER Rating : 630 kVA Rated Voltage : 22000 / 433 V Rated Current : 16.53 / 840 A Nos. of Phase : 03 Type of Cooling : ONAN Frequency : 50 Hz % Impedance : 5 % Vector Group : Dyn 11	SAMPLE IDENTIFICATION Serial No. : 021 Year of Mfg. : 2015 Make : M/s. Allianz Transformers Pvt. Ltd. ERDA Sample Code No.: ERDA-00103771	
TEST DETAIL Lightning impulse test with chopped on the tail on all the three phases of HV terminals at 125 kVp. ENCLOSURE: DRG. No.: (1) AT/GA/630/22/1 (2) AT/NP/630/22/1 TEST WITNESSED BY: ----- REMARKS : From the observation of enclosed oscillographic records, it is concluded that the transformer conforms to the requirements of the above mentioned test specification with respect to the test carried out.	TEST SPECIFICATION IS: 2026(Part -3):2009, Cl. No. 14.	
 PREPARED BY	 CHECKED BY	 A.S.KHOPKAR APPROVED BY
Note : 1. This report relates only to the particular sample received in good condition for testing at ERDA. 2. This report cannot be reproduced in part under any circumstances. 3. Publication of this report requires prior permission in writing from Director, ERDA. 4. Only the tests asked for by the customer have been carried out. 5. In case of any dispute, Vadodara will be the exclusive jurisdiction & shall be construed as where the cause has arised.		
Caution: ERDA is not responsible for the authenticity of photocopied or reproduced test reports. ERDA provides support to customers for verification of the authenticity of test reports issued by ERDA.		

TE 1726803